
#### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Timothy W. Davenport GLO contract number 102, dated July 20, 1863. Surveyor General record states: Set post for South 1/4 corner in mound of earth, with charred stake, pits, trench as per instructions.



## DESCRIPTION OF CORNER EVIDENCE FOUND:

No evidence found

See Survey Number 034-2001.

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2  $\frac{1}{2}$ " x 30" aluminum monument marked as shown below, 25" in the ground, from which:

### NEW BEARING TREES:

A 17 inch diameter Ponderosa Pine bears N 86°E, a distance of 6.41 ft, marked T3S R40E S35 BT.

A 15 inch diameter Douglas Fir bears S 26°E,86° a distance of 39.25 ft, marked T4S R40E S2 BT.

A 16 inch diameter Ponderosa Pine bears S  $31^{\circ}W$  a distance of 19.96 ft, marked T4S R40E S2 BT.

A 8 inch diameter Ponderosa Pine bears N43°W a distance of 16.10 ft, marked X BT.


Raised small mound of stone around monument.


I hereby certify that the corner was monumented on October 8, 2001. Witnesses: Norb Volny and Greg Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 2002





I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2219 to the bearing tree blaze.