
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Survey Number 022-2015

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At a position determined by survey, I set a  $5/8" \times 30"$  iron rod with a 2 4" aluminum cap marked as shown below, 28" in the ground. From which:

## **NEW BEARING OBJECTS:**

A 9" Ponderosa Pine bears North 34° East, a distance of 33.80 feet, marked NW 1/16 S1 BT.

A 9" Ponderosa Pine bears South 57° East, a distance of 33.25 feet, marked NW 1/16 S1 BT.

I set a steel fencepost approximately 1 foot North of corner monument.


I hereby certify that the corner was monumented on April 22, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR

Date Received 4/28/15

Date Filed By 4/28/15

File Number 099-2015R