
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

# T4S R40 E C-20



### DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey 039-2021

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 27" in the ground, with 2 1/2" aluminum cap marked as shown, from which:

NEW BEARING OBJECTS:
A 7" Ponderosa Pine bears North 25° East, a dist. of 13.45

ft., marked CE 1/16 S2 BT A 6" Ponderosa Pine bears North 21° West, a dist. of 12.20 ft., marked CE 1/16 S2 BT

Set steel fence post approx. 1.0 feet South

An East/West bearing fence line falls approx. 2 feet North

A fence corner to West and South bearing fence lines bears approx. 32 feet Easterly

I hereby certify that the corner was monumented on August 9, 2021.

Witness: Kyle Tucker

GRIFFITH & BLACTRAZZ 8 A GRY T4S R40E E 1/16 - C С S2 **OPLS 83571** 2021

REGISTERED **PROFESSIONAL** JRWEYYOR LAND JEFFREY S. HSU 83571

Renewal Date: June 30, 2023

UNION COUNTY **SURVEYOR** 

I used a steel tape and magnetic compass in the establishment of the new accessories. I used  $14\,^\circ$ East declination, the distances are to a  $60d\ \text{spike}$ driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.