## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by John H. Stone under GLO contract Number 235, dated July 6, 1875. Surveyor General field notes state:

Set a Pine Post 4 ft long 4 in in dia for 1/4 sec cor as per instructions. From which:
A Fir 16 in in dia bears due West 20 links distant.

# S 1

T4S R40 EC-21

## DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 022-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a  $2 \times "$  x 30" aluminum pipe with a  $2 \times "$  aluminum cap marked as shown below, 28" in the ground with a collar of stone 18" diameter.

# **NEW BEARING OBJECTS:**

An 8" Ponderosa Pine bears North 42° West, a distance of 21.75 feet, marked 1/4 S2 BT. A 4" Ponderosa Pine bears North 82° West, a distance of 16.45 feet, marked X BT. An 8" Ponderosa Pine bears South 19° West, a distance of 23.70 feet, marked 1/4 S2 BT. A 10" Ponderosa Pine bears South 79° West, a distance of 21.45 feet, marked X BT.

No suitable East trees.

I set a steel fencepost approximately 1 foot North of corner monument.


I hereby certify that the corner was monumented on April 20, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017



UNION COUNTY
SURVEYOR

Date Received 4/28/15

Date Filed By 4/28/15

File Number 098-2015R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.