
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

## T4S R40 E E-20



#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey 039-2021

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey I set a 5/8" x 30" iron pin, 24" in the ground, with 2 1/2" aluminum cap marked as shown and in a 2' diam. collar of stone, from which:

## **NEW BEARING OBJECTS:**

A 2'x2'x3' rock outcrop bears South 19°38' West, a dist. of 14.95 ft., marked X BO
A 2'x1'x3' rock outcrop bears North 37°40' West, a dist. of 107.00 ft., marked X BO


Set steel fence post approx. 1.0 feet North

A North/South bearing fence line falls approx. 28 feet West

A fence corner to East/West/North bearing fence lines bears approx. 32 feet Southeasterly

I hereby certify that the corner was monumented on August 6, 2021.

Witness: Kyle Tucker



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

UNION COUNTY
SURVEYOR

Date Received 8 35/31

Date Filed 8 35/31

Filed By 1 6 Man 1 6 Mary

File Number 036-2021 2

I used a Leica GS18 RTK GPS rover in the establishment of the new accessories. Basis of Bearing is as per Survey 039-2021. The distances and bearings are to the center of the "X".