


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner not previously established.



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None

SEE SURVEY NUMBER 034-2015

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At position determined by survey I set a 2½"x30" iron pin with 2½" aluminum cap, marked as shown, 29" in ground, from which:

**NEW BEARING OBJECTS:**

A 6 inch Douglas Fir bears North 32° East, a distance of 14.25 feet, marked CN 1/16 S12 BT.

A 6 inch Western Larch bears North 54° West, a distance of 3.70 feet, marked CN 1/16 S12 BT.


I set a steel fencepost approximately 1 foot North of the monument.

I hereby certify that the corner was monumented on May 26, 2015.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*[Signature]*  
OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2017



**UNION COUNTY  
SURVEYOR**  
Date Received 5/29/15  
Date Filed 5/29/15  
Filed By *[Signature]*  
File Number 107-2015R

I used a compass and steel tape in the establishment of the bearing trees. Magnetic declination used was 16° East. Distances are measured to a 60d spike in the right hand side of the root crown of the trees. Bearings are measured to a brass washer marked OPLS 83571 in the upper portion of the BT blaze.