


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 034-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey I set a 2½"x30" iron pin with 2½" aluminum cap, marked as shown, 29" in ground, from which:

NEW BEARING OBJECTS:

A 19 inch Douglas Fir bears South 33° East, a distance of 54.85 feet, marked NE 1/16 S12 BT.

A 20 inch Douglas Fir bears South 71° West, a distance of 21.60 feet, marked NE 1/16 S12 BT.

I set a steel fencepost approximately 1 foot South of the monument. Corner falls on South edge of logging road. Road bears N45°W/S45°E

I hereby certify that the corner was monumented on May 26, 2015.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

BAGETT - GRIFFITH & BLACKMAN

T4S R40E

NE 1/16 S 12

2015

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 5/29/15

Date Filed 5/29/15

Filed By [Signature]

File Number 108-2015R

I used a compass and steel tape in the establishment of the bearing trees. Magnetic declination used was 16° East. Distances are measured to a 60d spike in the right hand side of the root crown of the trees. Bearings are measured to a brass washer marked OPLS 83571 in the upper portion of the BT blaze.