


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner originally established by David Thompson under GLO contract number 103 dated September 3, 1863. Surveyor General field notes state:

Set post for 1/4 sec. corner in mound of earth with charred stake, pits, trench, as per instructions.

T 4 S R 40 E N-11



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None found.

See Survey 005-2020

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**

At proportionate position I set a 5/8" x 30" iron pin, 20" in the ground, with 2 1/2" aluminum cap, marked as shown below, with 2 ft. diam. mound of stone, from which:

**NEW BEARING OBJECTS:**

- A rock outcrop bears North 56°30' East a dist. of 17.76 ft., marked with chisel "X BO"
- A rock outcrop bears South 38° East a dist. of 24.20 ft., marked with chisel "X BO"
- A rock outcrop bears South 17°50' West a dist. of 15.36 ft., marked with chisel "X BO"
- A rock outcrop bears North 30°30' West a dist. of 10.78 ft., marked with chisel "X BO"

Set steel fence post approx. 1 ft. East


East/West fence line falls approx. 170 feet South.

I hereby certify that the corner was monumented on February 21, 2020.

Witness: Kyle A. Tucker



Renewal Date: June 30, 2021



**UNION COUNTY SURVEYOR**

Date Received 3/17/20

Date Filed 3/17/20

Filed By [Signature]

File Number 007-2020M

I used a Leica GS 18 in the establishment of the new accessories. Basis of Bearing is as per Survey 005-2020, the distances and bearings are to the center of the chiseled "X".