CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously established.

T4S R40 E N-12 S 21

DESCRIPTION OF CORNER EVIDENCE FOUND:

None found.

See Survey 005-2020

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position I set a 5/8" x 30" iron pin, 22" in the ground, with 2 1/2" aluminum cap marked as shown below, in a 2 ft. diam. mound of stone from which:

NEW BEARING OBJECTS:

A 5/8" x 30" iron pin bears SOUTH a dist. of 20.00 ft., with 1 1/2" aluminum cap marked S A 5/8" x 30" iron pin bears WEST a dist. of 20.00 ft., with 1 1/2" aluminum cap marked W RP.

Set steel fence post approx. 1 ft. West

An East/West/South fence corner bears Southeast approx. 70 ft. I hereby certify that the corner was monumented on February 21, 2020. Witness: Kyle A. Tucker

> REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2021

T4S R40E S16 E 1/16 S21 2020 **OPLS 83571**

UNION COUNTY SURVEYOR

I used a Leica GS 18 in the establishment of the new accessories. Basis of Bearing is as per Survey 005-2020, the distances and bearings are to the center of the aluminum caps.