


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner originally established by David Thompson under GLO contract number 103 dated September 3, 1863. Surveyor General field notes state:

Set post for corner to secs. 22, 22, 27, and 28 in mound of earth with charred stake, pits, trench, as per instructions.

T 4 S R 40 E R-13



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Found a 4' diameter embedded mound of stone in an East/West fence line. Examination 300 ft. to the East and West indicates that rock jacks are few in this area.

See Survey 005-2020

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**


At center of found mound of stone I set a 2 1/2" x 30" aluminum pipe with 3" aluminum cap, 21" in the ground, with 4' collar of stone, and marked as shown below, from which:

**NEW BEARING OBJECTS:**

- A 5/8" x 15" iron pin bears South 89°40' East a dist. of 17.25 ft., marked SE RP.
- A 5/8" x 15" iron pin bears North 5°20' West a dist. of 19.95 ft., marked N RP.
- A 5/8" x 15" iron pin bears South 4° East a dist. of 22.13 ft., marked S RP.
- A 5/8" x 15" iron pin bears South 88° West a dist. of 16.97 ft., marked NW RP.

Falls in an East/West fence line.

I hereby certify that the corner was monumented on March 3, 2020.  
Witness: Kyle A. Tucker



**UNION COUNTY SURVEYOR**

Date Received 3/17/20

Date Filed 3/17/20

Filed By [Signature]

File Number 010-202012

I used a Leica GS 18 in the establishment of the new accessories. Basis of Bearing is as per Survey 005-2020, the distances and bearings are to the center of the aluminum caps.