


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR

Date Received 10-20-86
 Date Filed 10-27-86
 By G. LANGRISH, DEPUTY
 File No. 190-86 R

See map of survey number 29-86 filed in the office of the Union County Surveyor

Description of monument and accessories established to perpetuate the

original location of this corner: At position determined by survey, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground

From which:


A 12 inch Douglas Fir bears S 14° E, 6.23 feet, marked NW 1/16 S 5 BT.

A 16 inch Tamarack bears N 69° W, 8.45 feet, marked NW 1/16 S 5 BT.

Set a steel fence post approximately 5 feet South with a 54-9 sign attached.

Corner set; 8/29/86

Witness: Greg Blackman



REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by

(COUNTY OFFICIAL)

(DEPUTY)