


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR

Date Received 10-20-86

Date Filed 10-27-86

By G. LANGLITZ DEPUTY

File No. 191-86 R

See map of survey number 29-86 filed in the office of the Union County Surveyor
 Description of monument and accessories I established to perpetuate the
 original location of this corner: At position determined by survey, I set a 2 1/2"x30"
 aluminum pipe with aluminum cap marked as shown, 28 inches in the ground
 From which:

A 10 inch Tamarack bears N 26° E, 7.54 feet, marked CN 1/16 S5 BT.

A 12 inch Douglas Fir Bears N 56° W, 10.56 feet, marked CN 1/16 S5 BT.


Set a steel fence post approximately 5 feet East with a 54-9 sign attached.

Corner set; 9/2/86

Witness: Rick Robinson

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644



Brass washer marked OPLS 644 nailed to BT blaze.
 Used steel tape and magnetic compass with 20° East
 declination. Distances to the BTs are to a 50d
 spike set in right side of tree when facing tree,
 unless otherwise stated.

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19....

..... by
 (COUNTY OFFICIAL) (DEPUTY)