
CERTIFIED RECORD OF LAND CC MONUMENTATION


History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:

NONE



See survey. number 29-86 filed in the office of the Union County Surveyor. Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I chisled a 4 inch cross in a rock face, and set a Witness Corner which was a 2½1x30" aluminum pipe with aluminum cap marked as shown, 15 inches in the ground and raised a mound of stone with a 3 foot base to top of cap. Witness corner is set \$ 0° 32 27" E, a distance of 25.00 feet from the true corner.


New BTs from WC.

A 12 inch Douglas Fir bears S 76° E, 30.27 feet, marked X BT.

A North face of rock outcrop, 40 feet high running south and west bears \$ 82° W, 4.10 feet marked X B0

Set steel fence post approximately 5 feet North with a 54-2 and a 54-9 sign attached.

Corner set: 8/21/86
Witness: Greg Blackman, Rick Robinson, Greg Blackman Jr.



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 10, 1964

DUANE I. GRIFFITH

Brass washer marked OPLS 644 nailed to BT Blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d Spikeset in right side of tree when facing tree, unless otherwise stated.

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE -1983-793-276

瓜-25