


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner originally established by Henry M. Thatcher under GLO contract number 320 dated April 1, 1879. Surveyor General record states;

Set stone 15x13x3 for 1/4 sec cor
Raised stone mound at cor



No record of subsequent remonumentation found in county records.
Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR
Date Received 10-20-86
Date Filed 10-27-86
By G. LANGLITZ DEPUTY
File No. 198-86 R

See map of survey number 29-86 filed in the office of the Union County Surveyor
Description of monument and accessories established to perpetuate the original location of this corner: At the proportioned position, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground with a small mound of stone around cap, from which:


A 16 inch Douglas Fir bears S 10° W, 6.32 feet, marked 1/4 S8 BT.

An 11 inch Tamarack bears N 86° W, 21.88 feet, marked 1/4 S5 BT.

Corner set 8/18/86

Witness: Greg Blackman, Rick Robinson

Set a steel fence post approximately 5 feet East with a 54-9 sign attached.



Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19....

..... by
(COUNTY OFFICIAL) (DEPUTY)