
CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:

NONE



See map of survey number 29-86 filed in the office of the Union County Surveyor Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½1x3011 aluminum pipe with aluminum cap marked as shown, 26 inches in the ground and raised a mound of stone with a 2 foot base to top of cap, from which:


An 18 inch Douglas Fir bears N 1° E, 2.78 feet, marked W 1/16 S4 Bt

A 10 inch Tamarack bears S 6° W, 7.89 feet, marked W 1/16 S9 BT.

Set steel fence post approximately 5 feet East with a 54-2 and 54-9 sign attached.

Corner set 8/26/86

Witness: Gregory T. Blackman, Rick Robinson



Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

REGISTERED PROFESSIONAL

Office of	County of
State of, I hereby certify that the within instrument was filed in this office	
for record on the day of	, 19
by	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276