


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner originally established by Henry M. Thatcher under GLO contract number 320 dated April 1, 1879. Surveyor General record states:

Set stone 12x10x8 for 1/4 sec cor  
Raised mound of stone at cor



No record of subsequent remonumentation found in county records.  
Description of corner evidence found:

A stone 11"x10"x7" marked 1/4 with part of "S" visible, in a small mound of stone.


See survey number 29-86 filed in the office of the Union County Surveyor.  
Description of monument and accessories I established to perpetuate the original location of this corner: At stone position, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown 28 inches in the ground, from which:

A 7 inch Tamarack bears S 33° W, 16.18 feet, marked 1/4 S 9 BT.

An 11 inch Tamarack bears N 59° W, 17.20 feet, marked 1/4 S 4 BT.

Set a steel fence post approximately 5 feet East with a 54-9 sign attached.  
Buried stone south of the cap.

Corner set : 8/26/86  
Witness: Greg Blackman, Rick Robinson.



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
644

Brass washer marked OPLS 644 nailed to BT blaze.  
Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

UNION COUNTY  
SURVEYOR

(DEPUTY)

Form R6-7100-57 (9/71)

Date Received 10-20-86

Date Filed 10-27-86

By G. LANGRIS, DEPUTY

File No. 201-86R

☆ U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

IV-5