
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner originally established by Henry M. Thatcher under GLO contract number 320 dated April 1, 1879. Surveyor General record states:

Set stone 16x16x4 for cor to secs 3,4,9 and 10 Raised stone mound at corner



No record of subsequent remonumentation found in County Record. Description of corner evidence found:

A stone 16"x15"x3", marked with 5 grooves on the North and 1 groove on the East and West, grooves on the South not visible. Stone is broken at the top.

See map of survey number 29-86 as recorded with the Union County Surveyor. Description of monument and accessories I established to perpetuate the

original location of this corner: At the stone position. I set a $2^{12}1\times30^{11}$ aluminum pipe with aluminum cap marked as shown, 180 in the ground and raised a mound of stone with a 3 foot base to top of cap, from which:

A 14 inch Lodgepole Pine bears N $18^{\rm o}$ E, 22.25 feet, marked T4S R41E S 3 BT.

A 17 inch Spruce bears S 24° E, 23.27 feet, marked T4S R41E S10 BT.


A 6 inch Spruce bears S 53° W, 46.84 feet, marked X BT.

A 25 inch Spruce bears N 58° W, 9.00 feet, marked T4S R 41 E S 4 BT.

Set a steel fence post approximately 5 feet North with a 54-4 sign attached. Buried stone South of cap.

Corner set 8/12/86

Witness: Greg Blackman, Rick Robinson



PROFESSIONAL AND SURVEYOR OREGON JULY 10, 1964 DUANE I. GRIFFITH

REGISTERED

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of County of....., I hereby certify that the within instrument was filed in this office for record on the...... day of......UNION COUNTY (COUNTY OFFICIAL) SURVEYOR (DEPUTY)

Form R6-7100-57 (9/71)

Date Received 10-20-86

☆U.S. GOVERNMENT PRINTING OFFICE - 1983 - 793 - 276

E-13