CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 052-2015

T4S R41E F-01

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron rod with a 2 ½" aluminum cap marked as shown below, 27" in the ground. From which:

NEW BEARING OBJECTS:

A 6" Ponderosa Pine bears South 74° East, a distance of 34.45 feet, marked N 1/16 S7 BT. A 5" Ponderosa Pine bears South 80° West, a distance of 13.95 feet, marked N 1/16 S12 BT.

I set a steel fencepost approximately 0.5 foot North of corner monument.

I hereby certify that the corner was monumented on August 28, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND STRIJEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

UNION COUNTY
SURVEYOR

Date Received 8 3 1 5

Date Filed By 4 6 Mun

Filed By

133-2015R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.