### CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

### DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 052-2015

# S 7

T4S R41E F-03

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron rod with a 2 ½" aluminum cap marked as shown below, 25" in the ground. From which:

#### **NEW BEARING OBJECTS:**

A 6" Ponderosa Pine bears North 17° East, a distance of 34.55 feet, marked CN 1/16 S7 BT. An 11" Douglas Fir bears North 83° West, a distance of 27.15 feet, marked CN 1/16 S7 BT.

I set a steel fencepost approximately 1 foot West of corner monument.

I hereby certify that the corner was monumented on August 28, 2015.

Witness: Thomas J. Kopp

REGISTERED PROFESSIONAL LAND SURVEYOR

June 2, 2010
JEFFREY S. HSU
83571

OREGON

Renewal Date: June 30, 2017

T4S R41E C S7 C 2015 OPLS 83571

UNION COUNTY SURVEYOR

Date Received 8/31/1

Date Filed 8/31/15

Ello Number 134-2015 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.