


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 4 S R 41 E F-05



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 052-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron rod with a 2 1/2" aluminum cap marked as shown below, 27" in the ground. From which:

NEW BEARING OBJECTS:

An 8" Spruce bears South 54° East, a distance of 23.80 feet, marked N 1/16 S8 BT.
An 8" Spruce bears South 71° West, a distance of 90.10 feet, marked N 1/16 S7 BT.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on August 28, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017


**UNION COUNTY
SURVEYOR**

Date Received 8/31/15

Date Filed 8/31/15

Filed By [Signature]

File Number 132-2015R



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 15° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.