
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Henry M. Thatcher under GLO contract number 320, dated April 1, 1879. Surveyor General record states:

Set stone 19"x4"x4" for 1/4 Sec. Cor. Raised stone mound at



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey Number 022-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap, marked as shown below, 25" in the ground, in a mound of stone 2 ft. diam., from which:

A 13 inch Ponderosa Pine bears North 35° East, a distance of 54.90 feet, marked 1/4 S8 BT. An 18 inch Ponderosa Pine bears South 58° East, a distance of 5.62 feet, marked 1/4 S8 BT. A 13 inch Ponderosa Pine bears South 71° West, a distance of 34.75 feet, marked 1/4 S7 BT. A 9 inch Ponderosa Pine bears North 53° West, a distance of 69.75 feet, marked 1/4 S7 BT.

I hereby certify that this corner was monumented May 7, 2013.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

ORÉGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

UNION COUNTY SURVEYOR

Data Bassimad

Filed By

1516 Number 4()8-7013R

I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. I place a brass washer marked OPLS 83571 in the lower blaze of the new bearing trees.