


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR

Date Received 10-20-86

Date Filed 10-27-86

By G. LANGLITZ DEPUTY

File No. 205-86 R

See map of survey number 29-86 filed in the office of the Union County Surveyor

Description of monument and accessories established to perpetuate the original location of this corner: At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 22 inches in the ground and raised a mound of stone with a 3 foot base to top of cap, from which:

A 26 inch Ponderosa Pine bears N 45° E, 3.64 feet, marked CW 1/16 S9 BT.

A 17 inch Douglas Fir bears S 36° W, 15.72 feet, marked CW 1/16 S9 BT.


Set a steel fence post approximately 5 feet West with a 54-9 sign attached.

Corner set : 8/28/86

Witness: Greg Blackman, Rick Robinson

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644



Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by

(COUNTY OFFICIAL)

(DEPUTY)