

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner originally established by Henry M. Thatcher under GLO contract number 320 dated April 1, 1879. Surveyor General record states:

Marked a fir 5 in dia for 1/4 sec cor from which;

A pine 6 in dia bears S20°E 23 lks dist

A fir 7 in dia bears N35°W 41 lks dist



No record of subsequent remonumentation found in county records.

Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR

Date Received 10-20-86

Date Filed 10-27-86

By G. LANGLITZ, DEPUTY

File No. 207-86 R

See survey number 29-86 filed in the office of the Union County Surveyor.

Description of monument and accessories I established to perpetuate the original location of this corner: At the proportionate position, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 24 inches in the ground, from which:

An 8 inch Spruce bears S 35° E, 26.52 feet, marked 1/4 S10 BT.

A 6 inch Tamarack bears S 34° W, 27.41 feet, marked 1/4 S9 Bt.

Set a steel fence post approximately 5 feet North with a 54-9 sign attached.


Corner set : 8/25/86

Witness: Greg Blackman, Rick Robinson

REGISTERED PROFESSIONAL LAND SURVEYOR

Duane I. Griffith

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644



Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by

(COUNTY OFFICIAL)

(DEPUTY)