CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously set.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 ½" x 30" aluminum pipe with a 2 ½" aluminum cap, marked as shown below, 20" in the ground with a mound of stone 2 foot base to top of cap. From which:

SEE SURVEY NUMBER 047-2015

NEW BEARING TREES:

- A 3" Western Larch bears North 74° West, a distance of 15.15 feet, marked Y BT.
 A 6" Western Larch bears South 30° East, a distance of 43.45 feet, marked C 1/4 S17 BT.
 A 4" White Fir bears South 17° West, a distance of 49.90 feet, marked C 1/4 S17 BT.
 A 3" Western Larch bears North 17° West, a distance of 13.35 feet, marked X BT.

No suitable trees available in Northeast quadrant.

Set a steel fence post approximately 2 feet North of monument.

I hereby certify that this corner was monumented on July 27, 2015.

Witness: Thomas J. Kopp

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON June 2, 2010 JEFFREY'S. HSU 83571

Renewal Date: June 30, 2017

GRIFFITH BLACTAPZ T4S R41E S17 C 1/4 2015 **OPLS 83571**

T4S R41 EL-07

17

S

UNION COUNTY **SURVEYOR**

File Number 131-2015 R

I used a steel tape and magnetic compass in the establishment of the new bearing trees. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the new bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.