
CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment: Corner originally established by Henry M. Thatcher under GLO Contract number 320 dated April 1, 1879. Surveyor General record states:

Set stone $19^{11}\times11^{11}\times9^{11}$ in a mound of stone for $\frac{1}{4}$ section corner.



No record of subsequent remonumentation found in county records. Description of corner evidence found:

Found stone 18''x11''x8'' in a mound of stone marked $\frac{1}{4}S$.



Description of monument and accessories I established to perpetuate the


original location of this corner: At stone position, I set a 2½'x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground and raised a small mound of stone. Buried the stone East of the cap. From which:

A 9 inch Tamarack bears N 3° E, 28.84 feet, marked $\frac{1}{4}$ S 16 BT.

A 10 inch Tamarack bears S 36° W, 17.33 feet, marked $\frac{1}{4}$ S 21 BT.

I set a steel fence post approximately 5 feet East with a 54-9 sign attached.

Corner set 7/17/86 Witness: Rick Robinson



PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1984

DUANE I. GRIFFITH

REGISTERED

Brass washer marked OPLS 644 nailed to BT. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
State or, I hereby certify the for record on the day of	at the within instrument was filed in this office ······. , 19····.
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE-1983-793-276

II-25

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Henry M. Thatcher under GLO Contract number 320 dated April 1, 1879. Surveyor General record states:

Set stone 19"x11"x9" in a mound of stone for 1/4 section corner.

On July 17, 1986, corner brought to county standard by Duane I. Griffith. Union County Monumentation record 212-86R states:

Found stone 18"x11"x8" in a mound of stone marked 1/4S. At stone position, I set a 2 ½"x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground and raised a small mound of stone. Buried the stone East of the cap.



From which:

A 9 inch Tamarack bears N 3° E, 28.84 feet, marked 1/4 S 16 BT A 10 inch Tamarack bears S 36° W, 17.33 feet, marked 1/4 S 21 BT

Set steel fencepost approximately 5 feet East with a 54-9 sign attached

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 2 $\frac{1}{2}$ "x30" aluminum pipe with aluminum cap 2" above ground marked as shown, with a 1' collar of stone.

From which:

A 13" Western Larch bears N 3° E 28.8 feet, alive and vigorous with healed blaze A 16" Western Larch bears S 36° W 17.3 feet, alive and vigorous with healed blaze

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the Aluminum pipe monument,

NEW BEARING TREES:

A 6" Western Larch bears S 77° E 37.15 feet, marked 1/4 S21 BT A 12" Western Larch bears N 60° W 31.35 feet, marked 1/4 S16 BT

Fence corner falls 2 feet West of monument. Fences bear East and South. I hereby certify that the corner was perpetuated July 7, 2017.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

T4S R41E

S 16

1/4

S 21

1986

OPLS 644

UNION COUNTY
SURVEYOR

Date Received 7 (2 (7)

Date Filed By County

File Number 021-2011 R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.