


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner originally established by Henry M. Thatcher under GLO contract number 320 dated April 1, 1879. Surveyor General record states:

Set stone 13"x9"x5" in a mound of stone for the 1/4 section corner between sections 20 and 21.



No record of subsequent remonumentation found in county record.
Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR

Date Received 10-20-86

Date Filed 10-27-86

By G. LANGLITZ, DEPUTY

File No. 251-86 R

See map of survey number 31-86 filed in the office of the Union County Surveyor
Description of monument and accessories I established to perpetuate the

original location of this corner: At proportionate position, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 26 inches in the ground and raised a mound of stone with a 3 foot base to top of cap, from which:


A 17 inch White Fir bears N 19° E, 28.53 feet, marked 1/4 S 21 BT.

A 26 inch Spruce bears N 82° W, 30.50 feet, marked 1/4 S 20 BT.

Set a steel fence post approximately 5 feet North with a 54-9 sign attached.

Corner set: 9/16/86

Witness: Greg Blackman, Rick Robinson



Brass washer marked OPLS 644 nailed to BT Blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d Spikeset in right side of tree when facing tree, unless otherwise stated.

REGISTERED PROFESSIONAL LAND SURVEYOR

Handwritten signature of Duane I. Griffith

OREGON
JULY 10, 1984
DUANE I. GRIFFITH
644

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)