
CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner not established in original survey



Description of corner evidence found:

NONE



See map of survey number 31-86 filed in the office of the Union County Surveyor Description of monument and accessories I established to perpetuate the


original location of this corner: At position determined by survey, I set a $2\frac{1}{2} \times 30^{11}$ aluminum pipe with aluminum cap marked as shown, 24 inches in the ground and raised a mound of stone with a 3 foot base to top of cap, from which:

A 14 inch Douglas Fir bears East 19.82 feet, marked C4 S21 BT.

An 8 inch Tamarack bears S 80° W, 5.28 feet, marked $C\frac{1}{4}$ S21 BT.

Set a steel fence post approximately 3 feet North with a 54-9 sign attached.

Corner set: 9/18/86
Witness: Greg Blackman, Rick Robinson



OREGON
JULY 10, 1994

DUANE I. GRIFFITH

644

SURVEYOR

REGISTERED PROFESSIONAL

Brass washer marked OPLS 644 nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Distances to the BTs are to a 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
State of,	I hereby certify that the within instrument was filed in this office
for record on the day of	, 19
•••••	by
(COUNTY OFFICIAL	

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983 -793-276

