


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by H.M. Thatcher under contract no. 320, dated April 1, 1879. Surveyor General field notes state: Set Stone 21x9x8 for 1/4 Sec. Cor. Raised stone mound at Cor.

T 4 S R 41 E R-07



DESCRIPTION OF CORNER EVIDENCE FOUND:

No remaining evidence found.

SEE SURVEY NUMBER 035-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2" aluminum pipe with 2 1/2" aluminum cap, marked as shown below, 25 inches in the ground, in a collar of stone 2 ft. diam., from which:

NEW BEARING TREES:

- A 12" Ponderosa Pine bears North 52° East, a distance of 32.15 feet, marked 1/4 S20 BT.
- A 10" Ponderosa Pine bears South 28° East, a distance of 44.10 feet, marked 1/4 S29 BT.
- A 13" Ponderosa Pine bears South 83° West, a distance of 48.20 feet, marked 1/4 S29 BT.
- A 14" Ponderosa Pine bears North 22° West, a distance of 54.90 feet, marked 1/4 S20 BT.

Set a fencepost approx. 1 ft. North of the corner.


I hereby certify that the corner was monumented August 9, 2017.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



**UNION COUNTY
SURVEYOR**

Date Received 8/18/17

Date Filed 8/18/17

Filed By [Signature]

File Number 033-2017R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the new trees. Distance is to a spike set in the root crown of the side of the new trees.