
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Corner not previously established



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established
See Union County survey number 29-88



Description of monument and accessories I established to perpetuate the


original location of this corner: At the position determined by survey, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, from which;

New Bearing Tree and Bearing object; A 5/8"x30" iron pin with plastic cap marked BGA SURVEY MARKER bears North, 3.33 feet A 23 inch diameter Ponderosa Pine bears S39°W, 48.28 feet marked NW1/16 S30 BT

Set a steel fencepost approximately 3 feet North with 54-9 sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on July 27, 1988.

Witness: Jeff Petersen



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 17, 1000
RICK G. ROBINSON
2219

I used a steel tape and magnetic compass in the establishment of new accessories. I used 18° magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.

Office of	County of
State of , I hereby certify that the within instrument was filed in this office	
for record on the day of	, 19
by	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

GPO---788-276