CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T 4S R 41 E S-03

S 30

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 025-2010

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron rod with 2 ½" Aluminum Cap marked as shown, 29 ins. in the ground, from which:

A 5 in. diam. White Fir bears South 32° East, a distance of 5.61 feet, marked X BT.

A 19 in. diam. Douglas Fir bears South 68° West, a distance of 40.10 feet, marked CN 1/16 S30 BT.

I set a steel fencepost 1 ft. North of corner monument.

I hereby certify that the corner was monumented on October 22, 2010.


Witness: Jeff Hsu, Gregory T. Blackman, Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFERY S. HSU
83571

Renewal Date: June 30, 2011



I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. I place a brass washer marked OPLS 83571 in the lower BT blaze.