# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

# T4S R41 ET-06 S 29

#### DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

### SEE SURVEY NUMBER 035-2017

### DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

## TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" iron pin with 2 1/2" aluminum cap, marked as shown below, 26 inches in the ground, from which:

#### NEW BEARING OBJECTS:

A 6" Ponderosa Pine bears South 29° East, a distance of 5.05 feet, marked CW 1/16 S29 BT. A 16" Ponderosa Pine bears South 66° West, a distance of 23.40 feet, marked CW 1/16 S29 BT.


Set a fencepost approx. 1 ft. North of the corner. I hereby certify that the corner was monumented August 10, 2017.

Witness: Kyle Tucker

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON JEFFREY S. HSU 83571

Renewal Date: June 30, 2019

UNION COUNTY **SURVEYOR** Date Filed



I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the new trees. Distance is to a spike set in the root crown of the side of the new trees.