
ATIFIED RECORD OF LAND CORNER MONUMENT TION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Henry M. Thatcher under GLO contract number 320, dated April 1, 1879. Surveyor General record states:

Set stone 17x15x7 for 1/4 Sec. Cor. Raised stone mound at Cor



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 031-2012

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 $\frac{1}{2}$ "x30" aluminum pipe with 2 $\frac{1}{2}$ " aluminum cap, 26 inches in the ground, from which:

A 9 inch Ponderosa Pine bears North 43° East, a distance of 44.50 feet, marked 1/4 S29 BT. A 6 inch Ponderosa Pine bears South 42° East, a distance of 15.80 feet, marked 1/4 S32 BT. An 11 inch Ponderosa Pine bears South 86° West, a distance of 28.40 feet, marked 1/4 S32 BT. A 6 inch Douglas Fir bears North 22° West, a distance of 41.40 feet, marked 1/4 S29 BT.


I set a steel fencepost 1 foot North of the corner monument. I hereby certify that the corner was monumented on September 24, 2012.


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFERY S. HSU
83571

Renewal Date: June 30, 2013





I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. I place a brass washer marked OPLS 83571 in the lower blaze of the new accessories.