

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Henry M. Thatcher under GLO contract number 320, dated April 1, 1879. Surveyor General record states:

Set stone 14x12x4 for Cor. to Secs. 28, 29, 32 and 33.
 Raised stone mound at Cor.

T 4S R 41 E V-09



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 031-2012

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2"x30" aluminum pipe with 2 1/2" aluminum cap, 27 inches in the ground, in a collar of stone 2 ft. diameter, from which:

- A 17 inch Ponderosa Pine bears North 39° East, a distance of 12.60 feet, marked T4S R41E S28 BT.
- A 13 inch Ponderosa Pine bears South 36° East, a distance of 27.60 feet, marked T4S R41E S33 BT.
- A 17 inch Douglas Fir bears South 21° West, a distance of 17.00 feet, marked T4S R41E S32 BT.
- A 16 inch Western Larch bears North 30° West, a distance of 24.10 feet, marked T4S R41E S29 BT.

I set a steel fence post 1 foot North of corner monument.

I hereby certify that the corner was monumented on September 24, 2012.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
June 2, 2010

JEFFERY S. HSU
83571

Renewal Date: June 30, 2013

BAGETT - GRIFFITH & BLACKMAN

T 4 S R 41 E

S 29	S 28
S 32	S 33

2012

PLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 9/28/12

Date Filed 9/28/12

Filed By R. ROBINSON, DEPUTY

File Number 041-2012R

I used a steel tape and magnetic compass in the establishment of the accessories. I used 16° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. I place a brass washer marked OPLS 83571 in the lower blaze of the new accessories.