CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history

Cap Stamped
T 5 S
C 1/4
S 9
R 34 E
1978
ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a $2\frac{1}{2}$ " brass cap on a 30" galv. iron pipe, and stamped as shown above, in the ground, and placed a large mound of stone around the monument.

New bearing trees:
A pine 9" dia. bears N 56 W, 58.46 feet scribed \$\frac{1}{4}\$ S9 BT.
A pine 8" dia. bears S 40 E, 36.11 feet scribed \$\frac{1}{4}\$ S9 BT.

	F		CIST		Al	1		
			SU			17		
_	7	in-z4	11	11	(11	7	
	200	Ve55	2	Va	-	VI.	tona	
	an		- 21	-		大	ton	-
	AME	8	REGO	-7.	8		ton	-

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnessas.

Crew Chief

Crew Chief

Instrument Man

this office
UNION COUNTY SURVEYOR
1 - Rocejved R GPO - 798:276