CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history of this corner.

#-9
DIAGRAM
Cap Stamped
T 5 S
S-1/16
S 8 | S 9
R 34 E
1978
ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a $2\frac{1}{2}$ " brass cap on a 30" galv. iron pipe and being stamped as shown in the above diagram, and having a large mound of stone placed around the monument.

New bearing trees:
A pine 5" dia. bears S 62 W, 41.98 feet and scribed 1/16 S 8 BT.
A pine 6" dia. bears S 53 E, 62.94 feet and scribed 1/16 S 9 BT.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON JULY 10, 1964 JAMES H. HAMBLETON 645 I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses:

Crew Chief

Milly

Instrument/Man

Office of	the within instrument was filed in th , 19	is office UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Date Received