
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishments

Original survey by General Land Office contract survey

The original notes read. Set a post from Which: A pine 9" in diam bears N42°E 47 lks dist marked T5S R34E S8BT; A tamarack 10" in diam bears N32°W 201ks dist marked T5S R34E S7BT; A pine 10 ins in diam bears S58°W 13 lks dist marked T5S R34E S18BT; # pine 8° in diam bears S22°E 30 lks dist marked T5S R34E S17 BT:



Description of corner evidence found:

Found A pine log down with scribe; bears N42°E Found A tamarack 18" in diam bears N32°W

REGISTERED OREGON MAY 4, 1956 VOELZ 381

Description of monument and accessories I established to perpetuate the original location of this corner

AT the position of the corner I set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. Pipe set to a depth of 20" and backfilled with stone and soil;

I stamped the disk

COR T53 R34E 37 318 317 ORE LIC 381 1969

From the monument the original bearing tree is; A tamarack 18" in diam bears N32°W 20 lks dist.

I set the following new bearing trees;
A tamarack 0" in diam bears N35 34.4 ft. marked T5S R34E S8BT;
A tamarack 20" in diam bears S10E 24.2 ft. marked T5S R34E SI3BT

A black pine 11 in diam bears S81 W 39.5 ft. dist marked T55 R34E S18BT; (distances measured to center of respective trees and marked with scribe)
I set a steel fence post with USFS sign 14-4 attached. I placed National
Forest boundary signs on the post indicating National Forest land to South and EAST.

Bearing tree signs were placed on the bearing trees shoulder high facing the corner.

Office of County surveyor County of Union State of Oregon , I hereby certify that the within instrum	UNION COUNTY
for record on the10 day of Sapt	clock 19.m., (signed)
	Date Filed
	By