History of original corner establishments

Original survey by General Land Office contract survey
The original notes read;
Set a post from which; A pine 5 indiam bears N50°E 123 Iks
narked T5S R34E S9BT;
A pine 6 in diam bears N12°W 354 lks dist marked T5S R34E S8BT.
A pine 4 in diam bears S87°E 156 lks marked T5S R34D S16BT
No other trees with in limits.

DIA	GRAM 55	R34EWM
	88	S 9
	S17	S16

C^OR T5S R34E

Description of corner evidence founds

Found a 8" snag with scribe at 387 E 156 lks dist.

Description of manument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 24" and backfilled with stone and soil.

I stamped the disk

From the monument the original bearing trees are none.

I set the following new bearing trees;

A pine (black) 8" in diam bears N49E 152.5 ft. marked

1969

T5S R34E S34E S16BT.; A pine (black) 12" in diam bears S84°E 97.2 ft.

marked T5S R34E S16BT.; A black pine 26" in diam bears S55°W

541 ft. marked T5S R34E S17BT; A black pine 7" in diam bears N10°W

237.4 ft. marked T5S R34E S8BT; (trees measured to respective centers and marked with scribe) I set a steel fence post with USFS sign 54-4 attached.

Bearing tree sign were placed on bearing trees shoulder high facing the monument.

Office ofCounty surveyor	UNION COUNTY	
State of Oragon , I hereby certify that the within instrument was filed	in this office	
County surveyor	m., (algned) Date Received	
(COUNTY OFFICIAL)	Date Filed	
	Ву	
	File No. 560-84R	