History of original corner establishment:

The original survey made by General Land Office Contract survey. The original notes read; Set a post from which; A pine 48" in diam bears S37°E 64 lks dist marked \$\frac{1}{4}\$SBT; A pine 6" in diam bears N35°W 131 lks dist marked \$\frac{1}{4}\$SBT;

J-15

DIAGRAM

T5S R34EWM

S10
S15

A 7" Black pine bears N35°W 131 lks with scribe.
A pine stump 40" in diam bears S37°E with scribe;

REGISTERED
OREGON
LAND SURVEYOR

MAY 4, 1956

BAMES G. VOELZ
381

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 2" galvanized pipe 30" long with a bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 20" and back filled with stone and soil.

I stamped the disk

From the monument the original bearing tree is;

A Black pine 7" in diam bears N35°W 131 lks dist.

I set new bearing tree as follows; A pine 24" in diam bears S7°W 48.7 ft. dist to center of tree and marked ‡SBT with scribe; I set a steel fence post with USFS sign 54-4 attached. USFS bearing tree signs were placed on bearing trees shoulder high and facing the monument.

COR T5S R34E S10 S15 ORE LIC 381 1969

County survey	of Sept	erify that the within	a Instrument was fil	In the same of the same of the same of the same
			(DRPUTY)	Date Received
				Date Filed
				Ву
	, .			File No. 564-84 R