CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM
Cap Stamped
T 5 S
N-C-1/16
S 15
R 34 E
1978
ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a $2\frac{1}{2}$ " brass cap in a 30" galv. iron pipe, and stamped as shown above, in the ground, and placed a large mound of stone around the monument.

New bearing trees:
A pine 5" dia. bears N 02 E, 14.46 feet scribed 1/16S S 15 BT.
A pine 5" dia. bears S 04E, 15.00 feet scribed 1/16S S 15 BT.

PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1364

JAMES H. HAMBLETON
645

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses:

Instrument Man

File No. 572-84R

Office of	County of	
State of, I hereby certify tha	•	this office
for record on the day of	, 19	SUBARAOR COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	
orm R6-7100-57 (9/71)		© m-Received ☆GPO—798-276 Date Filed
		Rv