CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history

DIAGRAM
Cap Stamped
T 5 S
C 1/4
S 16
R 34 E
1978
ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a $2\frac{1}{2}$ brass cap in a 30^m galv. iron pipe, and stamped as shown above, in the ground, and placed a large mound of stone around the monument.

New bearing trees:
A pine 8" dia. bears N 18 W, 35.92 feet scribed 1/4S S 16 BT.
A pine 8" dia. bears S 24 E, 7.88 feet scribed 1/4S S 16 BT.

REGISTERED
PROFESSIONAL
LAND. SURVEYOR

8-21-78

OREGON
JAMES H. HAMBLETON

645

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses:

Crew Chief

Instrument Man

File No 575-84 R

Office of	the within instrument was filed in	this office
Tor record on the day of by		IRTHON COMMITT
(COUNTY OFFICIAL)	(DEPUTY)	JUNIVEYOR
orm R6-7100-57 (9/71)		Orta Received ☆ GPO—798-276
		Date Filed