History of original corner establishments

Original survey by General Land Office contract survey.

The original notes read; Set a post from which; A pine 5" in diam bears S21°W 24 lks dist marked \$\frac{1}{4}\text{SBT} A pine 5" in diam bears S21°E 64 lks dist marked \$\frac{1}{4}\text{SBT}

1-13	
DIAGRAI T5S	••
S16	\$15

Description of corner evidence founds

Found- A black pine 14" in diam bears S21°W 24 lks in good condition.

REGISTERED
OREGON
LAND SURVEYOR

MAY 4, 1956
JAMES G. VOELZ
381

Description of manument and accessories I established to perpetuate the original location of this corner

AT the postion of the corner I set a 2" galvanized pipe 30" long with a bronze cap on top and 8" plate welded to bottom. The pipe set to a death of 12" and backfilled with stone and soil and raised a stone monument.

I stamped the disk

#COR T5S R34E S16 S15 ORE LTC 381 1969

From the corner the original bearing tree is; A black pine 14" in diam bears S21.W.

FAREL DIE TIEN ET 10 100

I set a new bearing tree as follows; A black pine 15" in diam bears S64°E 75.9 ft. measured from center of tree and marked with a scribe ‡S8T; I set a steel fence post with USFS sign 54-4 attached. National Forest boundary signs were placed on the post indicating NationalForest land to South and WEst. USFS bearing tree signs were placed on bearing trees shoulder high facing the corner.

Office of County surveyor	UNION COUNTY
Co surveyor	m Mis efficient RVEYOR
(COUNTY OFFICIAL)	Date Received
·	Date Filed
	Ву
	EL N 674 045