CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history

L-15 DIAGRAM Cap Stamped T 5 S C 1/4 R 34 E 1978 ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a $2\frac{1}{2}$ brass cap in a 30 galv. iron pipe, and stamped as shown above, in the ground, and placed a large mound of stone around the mountment.

New bearing trees:
A pine 5" dia. bears S 32 W, 21.75 feet scribed \$\frac{1}{4}\$S S 15 BT.
A pine 5" dia. bears S 87 E, 7.25 feet scribed \$\frac{1}{4}\$S S 15 BT.

REGISTERED	
PROFESSIONAL	
LAND SURVEYOR	
Ta MACIA	٠.
8-2/-78	

for record on the...... day of......, 19.....

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses: Crew Chief

D Suiles

OREGON Sylv 10. 1964	L.D. Suiley
JAMES H. HAMBLETON 645	Instrument Man
Office of	of

(COUNTY OFFICIAL) by(DEPUTY) Form R6-7100-57 (9/71)

State of......, | hereby certify that the within instrument was filed in this effice UNION COUNTY SURVEYOR

> Date Received ☆ GPO-798-276 Date Filed___

File No. 577-84 R