

53-69A

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

26

History of original corner establishment:


Original survey by General Land Office contract survey.

The original notes read; Set a stone 14x8x6 marked $\frac{1}{4}$ on face from which;

A pine 30" in diam bears N30°W 15 lks dist marked $\frac{1}{4}$ SBT;

A pine 10" in diam bears N34°E 93 lks dist marked $\frac{1}{4}$ SBT;

L-21



Description of corner evidence found:

Found - A pine 32" in diam bears N30°W 15 lks dist. and is in good condition
A pine 26" in diam bears N34°E 93 lks dist. and is in good condition
The stone with marking was found.

REGISTERED
OREGON
LAND SURVEYOR

James G. Voelz


MAY 4, 1966
JAMES G. VOELZ
381

Description of monument and accessories established to perpetuate the original location of this corner

At the position of the corner I set a 2" galvanized pipe 30" long with a bronze cap on top and a 8" plate welded to bottom. The stone was placed along side the pipe.

I stamped the disk

From the monument the original bearing trees are;
A pine 32" in diam bears N30°W 15 lks dist;
A pine 26" in diam bears N34°E 93 lks dist; (original trees)
I set a steel fence post with USFS sign 54-4 attached.
USFS bearing tree signs were placed on the bearing trees shoulder high facing the corner.



Office of County Surveyor County of Union
State of Oregon I hereby certify that the within instrument was filed by this office
for record on the 10 day of Sept 1969 at 10 o'clock
..... Co. surveyor by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

(signed)

Date Received _____

Date Filed _____

By _____

File No. 581-84 R