


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established in 1882, by Rufus S. Moore, under General Land Office Contract No. 451. Surveyor General's records state:
A pine 16" dia. marked $\frac{1}{4}$ S on west face, from which:
A pine 5" dia. bears N 50 W, 17 lks. dist. marked $\frac{1}{4}$ S BT.
A pine 5" dia. bears S 48 E, 15 lks. dist. marked $\frac{1}{4}$ S BT.



Description of corner evidence found:

At assumed corner location I found no trace of the original $\frac{1}{4}$ sec. corner nor any evidence of the bearing trees as there was evidence of a fire in the early 1900's through this area and of which possibly destroyed all evidence of the original corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

Assuming this corner to be lost, I then used single proportioning measurements to re-establish this $\frac{1}{4}$ sec. cor., thus I set a 2 $\frac{1}{2}$ " brass cap on a 30" galv. iron pipe, and being stamped as shown above, with a large mound of stone and dirt around, and of which buried the monument.

New bearing trees:

A tamarack 8" dia. bears N 36 W, 44.58 feet scribed $\frac{1}{4}$ S S15 BT.
A fir 6" dia. bears S 43 W, 13.50 feet scribed $\frac{1}{4}$ S S 22 BT.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James H. Hambleton
8-21-78

OREGON
JULY 10, 1984
JAMES H. HAMBLETON
645

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses: *Leonard C. Green*
Crew Chief
L. D. Hulley
Instrument Man

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received _____ ☆ GPO—798-276
Date Filed _____
By _____
File No <u>592-84R</u>