


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

N-22

No previous history



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 2 1/2" brass cap in a 30" galv. iron pipe, and stamped as shown above, in the ground, and placed a large mound of stone around the monument.

New bearing trees:

A pine 17" dia. bears N 66 W, 82.0 feet scribed 1/16S S 13 BT.
A pine 6" dia. bears S 40 W, 250.0 feet scribed 1/16S S 24 BT.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James H. Hambleton
8-21-78

OREGON
JAMES H. HAMBLETON
645

I hereby certify the above corner monument was re-established as herein described in August 1978.

Witnesses:

Leonard E. Green
Crew Chief

L. S. Huber
Instrument Man

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)


UNION COUNTY SURVEYOR
Date Received _____
☆ GPO—798-276
Date Filed _____
By _____
File No. <u>596-84R</u>

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. N-22

History of original corner establishment:

None.



Description of corner evidence found:

Found 2.5" brass cap on 2" iron pipe.
Cap is stamped;

Bearing trees found:

- A 21" L. Pine bears N66 1/4°W, 81.9 ft.,
scribed (1/16 S S13 BT).
- A 9" L. Pine bears S41 3/4°W, 250.4 ft.,
scribed (1/16 S S 24 BT).

T5S
N-1/16
S 13
S 24
R34E
1978
ORLS 645

*Brass cap by 645 is stamped wrong. N 1/16 should read W 1/16.

Corner by LS 645 is recorded on document #596-84R with the Union County Surveyor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found in a small slough alongside creek, level with surrounding ground. Take Road 5160-534 south to Fly Creek. Corner is 30 ft. south of creek.

I hereby certify the above described corner monument and/or accessories was established as described on June 23, 1984.

UNION COUNTY SURVEYOR
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>949-84 R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1979 DAVID E. SCOTT 1844

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

by

(DEPUTY)