CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. W-18

History of original corner establishment:

None

DIAGRAM

T5S R34E

NW 1/16 • S35

Description of corner evidence found:

No corner monument or other official accessories found.

Description of monument and accessories I established to perpetuate the Cap stamped; original location of this corner:

T5S R34E

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 16" above ground in mound of rock & earth.

NW 1/16 • S35

Set steel fence post 2.5 ft. north of corner.

RLS 1844 1984

New BT's:

7" Spruce bears N7 1/4°E, 36.3 ft., blazed & scribed: NW 1/16 S35 BT. 8" Spruce bears N83.5°W, 30.0 ft., blazed & scribed: NW 1/16 S35 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on east slope, 1100 ft. south of Lookout Creek. RoRdad 5160-190 to Road 5160-198 to Lookout Creek, west 1200 ft. along creek to posted line. south 1100 feet to corner.

I hereby certify the above described corner monument and/or accessories was established as described on August 23, 1984.

FWED REC PROFESSIONAL ID SURVEYOR wid L. Sett OREGON DAVID E. SCOTT 1844

Office of	County of	
for record on the day of	the within instrument was filed in this office UNION COUNTY , 19	
(COUNTY OFFICIAL)	(DEPUTY) I	
R6-7100-57 (9/71)	Date Received 10-17-84 10-24-84 Date Filed GPO-798-276	

Form F