


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

Index File No. X-19



Description of corner evidence found:

No corner monument or other official accessories found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Set 2/5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

T5S R34E
C 1/4•S35
RLS 1844
1984

New BT's:

A 5" Fir bears N50.5°W, 37.1 ft., blazed and scribed: C 1/4 S35 BT.
A 6" Tamarack bears S79°W, 42.3 ft., blazed & scribed: C1/4 S35 BT.


Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 850 ft. southwest of Rd. 5160. Location Poster on 12" fir on south side of the road says corner is N25°E, 175 ft.

I hereby certify the above described corner monument and/or accessories was established as described on August 25, 1984.



Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

