

86-69A


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

79

History of original corner establishment:

Original survey by General Land Office contract survey 1882.

The original notes state. Run north between section 35 and 36 and set a post for $\frac{1}{4}$ cor from which.
A pine 14" in diam bears N28°E 9 lks dist marked $\frac{1}{4}$ SBT;
A tamarack 18" in diam bears N54°W 13 lks dist. marked $\frac{1}{4}$ SBT;



Description of corner evidence found:
Found a tamarack snag 16" in diam with scribe.

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 604-84R

REGISTERED
OREGON
LAND SURVEYOR


James G. Voelz

MAY 4, 1969
JAMES G. VOELZ
381

Description of monument and accessories established to perpetuate the original location of this corner
At the position of the corner I set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. The pipe set to a depth of 20" and backfilled with stone and tamped soil.

I stamped the disk

The original bearing trees are unsatisfactory. I set the following new bearing trees. From the monument the new bearing trees are;
A tamarack 10" in diam bears N32°E 36.4 ft. dist marked $\frac{1}{4}$ SBT;
A fir 9" in diam bears S65°W 47.2 ft. dist marked $\frac{1}{4}$ SBT.
Distance measured to center of trees and marked with scribe. I set a steel fence post with USFS sign 54-4 attached. USFS bearing tree signs were placed on bearing trees shoulder high facing the corner.



Office of.....County.....surveyor..... County of.....Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 16 day of Sept 1969, at 8 o'clock A.m., (signed)
..... County surveyor by *James G. Voelz*
(COUNTY OFFICIAL) (DEPUTY)