


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-25 <sup>1</sup>

History of original corner establishment:

The range line between R34E and R35E was done by J. Cooper, under Contract No. 397, approved April 5, 1882. At this corner, he set a post, from which a 22" Pine bears S26°W, 27 lks. and a 6" Fir bears S21°E, 24 lks.



Description of corner evidence found:

No corner monument found.

Found 6" Fir, dead & down, marked (1/4 S BT).

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 8" above ground. Cap is stamped;  
Set steel fence post 4.0 ft. north of corner.

T5S
R34E R35E
1/4
S1   S6
1984
RLS 1844

New BT's:

- A 6" Tamarack bears S39.5°W, 119.1 ft., blazed & scribed: 1/4 S1 BT.
- A 9" P.Pine bears S3°E, 71.8 ft., blazed & scribed: 1/4 S6 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is 75 ft. southwest of water trough at Otis Spring. Rds 2444 & 2442.

I hereby certify the above described corner monument and/or accessories was established as described in June of 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1979 DAVID E. SCOTT 1844

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>10-17-84</u>
Date Filed <u>10-24-84</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>947-84 R</u>