## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established by General Land Office contract survey The original notes state; North between sections 9 and 10. Set post for corners 3, 4, 9, and 10 from which a;
Tamarack 15" dia. bears N?? E, 106 lks marked T5S R35E S3ET;
Tamarack 15" dia bears N68 W, 68 lks marked T5S R35E S4ET;
Tamarack 12" dia bears S29 W, 19 lks marked T5S R35E S9ET;
Pine ?" dia bears S24 E, 47 lks marked T5S R35E S10 ET;

	E-13		
DIAGRA	DIAGRAM		
<b>T</b> 5S	R35EWM		
3 4	s 3		
s 9	S 10		

## Description of corner evidence found:

In section 4, found stump with scribe.

In section 9, found 10" Tamarack down log with scribe.

In section 3, found 21" Tamarack with scribe in good shape.

## Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

COR R35E

I stamped the disk.

From the monument the original bearing tree was; Tamarack 21" dia bears N77°E, 106 lks marked TSS R35E S3 BT I established the following new bearing trees; Tamarack 12" dia N12 W at a distance of 57.5 ft. and scribed T53 R35E S4 BT Lodge Pole 6" dia S48 W at a distance of 36.8 ft. and scribed T53 R35E S9 BT Lodge Pole 8" dia 912°E at a distance of 22.8 ft. and scribed T5S R35E S10 BT

54	3 3
s 9	210
ORE I	IC 381

The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attached near the corner and indicated private land to the northeast, by placeing USFS sign 54-2 on the steel post.

for record on the 18 day of Augu	certify that the within instrument was filed st	DOMACION
(COUNTY OFFICIAL)	(DEPUTY)	to Received
	,	Onte Filed
		Ву
		516 Nr. 606-010

Form R6-7100-57 (9/66)

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under Contract No. 481, Rufus S. Moore set a post, from which a 15" Tamarack bears N77°E, 10 1ks., a 15" Tamarack bears N68°W, 68 1ks., a 12" Tamarack bears S29°W, 19 1ks., and a 7° Pine bears S24°E, 47 1ks.

Index File No. E-13

DIAGRAM	
T5S R35E	
4 3 9 10	
	- 1

Description of corner evidence found:

Cap is stamped:

T5S R35E

Found 3 1/4" brass capped iron pipe rising 9" above ground, by LS 381.

S4 S3 S9 S10

Bearing trees found:

22" W. Larch bears N77°E, 70 ft., scribing visible: T4S R35E.

ORE LIC 381 1969

13" W. Larch bears N12°W, 57.5 ft., scribing visible: T5S R35E S4. 14" W. Larch, dead & down, visible scribing: R35E. Original SW BT.

6" L. Pine, SW Quadrant, dead & Down, Blaze & scribing visible. 8" L. Pine, SE Quadrant, dead & down, blaze & scribing visible.

Found steel fence post 4 ft. south of corner with signs.

Description of monument and accessories I established to perpetuate the original location of this corner:

New BT's:

7" W. Larch bears S20 3/4°W, 71.6 ft., blazed & scribed: T5S R35E S9 BT. 20.5" W. Larch bears S78 1/4°E, 90.7 ft., blazed & scribed: T5S R35E S10 BT.

Attached brass disk stamped LS 1848 to base of each blaze. Painted blazes and attached signs as per <u>Standard Specifications</u> for <u>Cadastral Surveys</u>, USFS Region 6, March 1982.

To find corner, take Rd. 5115 to 5115-500. Take 5115-500 up hill 1/4 mile past intersection of 5115-520. Corner is N10°E, 250 ft. from tag on 4" W. Larch on left side of road.

Compass Declination: 19 1/2 °E Witness: Herb Hamerlynck

I hereby certify the above described corner monument and/or accessories was established as described in September of 1985.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

Office of	County of	
State of		ois office UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
orm R6-7100-57 (9/71)		Date Received 9~18-85
, ,		Date Filed 9-23-85